

General tools

 <p>51/1 51/6 51/16 51/35 57/38</p>	<p>Clamping devices Magnetic tools Hammers, lathe tools, scribers Files, saws Pipe cutters Benders</p>	<p>51</p>
 <p>52/1 52/14 52/19 52/20 52/23</p>	<p>Combination wrenches Sockets and driving tools: ¹/₄"-drive from 52/14 onwards ³/₈"-drive from 52/24 onwards ¹/₂"-drive from 52/32 onwards ³/₄"-drive from 52/45 onwards</p>	<p>52</p>
 <p>52/54 52/59 52/61 52/66</p>	<p>1"-drive from 52/47 onwards for turning and impact screwdrivers Hook wrench, hexagonal and TORX screwdrivers Adjustable wrenches, self-grip and strap wrenches</p>	<p>52</p>
 <p>52/73 52/77 52/88 52/107 52/108</p>	<p>Socket spanners Torque tools Slotted and crosstip screwdrivers Power tools Bit program Inspection tools</p>	<p>52</p>
 <p>53/0 53/8 53/23 53/31 53/46</p>	<p>Pliers, tweezers, sheathing and insulation strippers, crimping tools, knives Sheet metal shears, scrapers Scissors, manual deburrers Sheet metal punch, keyhole saw Riveting tools</p>	<p>53</p>
 <p>54/1 54/3 54/4 54/6</p>	<p>Welding and cutting torches Soldering units</p>	<p>54</p>
 <p>55/2 55/6 55/13 55/10 55/20</p>	<p>Screw extractors Pullers Industrial safety</p>	<p>55</p>
 <p>56/0 56/4 56/6 56/8 56/10 56/16 56/27</p>	<p>Oil devices, grease presses Pumps, hinged hoses Painting requirements Brushes, lamps Batteries Engraving devices</p>	<p>56</p>